



To use CMOS version of Si570:  
 Remove R25 and U8 from circuit board  
 and jumper between hole of R25  
 and hole connected to U8 pin 5